



aclon

[www.miraclon.com](http://www.miraclon.com)  
1057 East Henrietta Rd  
Rochester, NY 14623

| <b>Current Catalog Number</b> | <b>Replacement Catalog Number</b> | <b>Description</b>     | <b>Revised Gross Weight (KG)</b> |
|-------------------------------|-----------------------------------|------------------------|----------------------------------|
| 20402045                      | 20402045Y1                        | NXH 114 1270 1651 0015 | 71                               |
| 20395000                      | 20395000Y1                        | NXH 114 1270 2032 0015 | 86                               |
| 20402046                      | 20402046Y1                        | NXH 170 1270 1651 0010 | 69                               |
| 20394998                      | 20394998Y1                        | NXH 170 1270 2032 0010 | 84                               |

**FLEXCEL NXH 5065 & 5080 Plate Kit Catalog Numbers**

| <b>Catalog Number</b> | <b>Description</b>        |
|-----------------------|---------------------------|
| <b>KIT-20402045R</b>  | NXH 114 1270 1651 30 SETS |
| <b>KIT-20395000R</b>  | NXH 114 1270 2032 30 SETS |
| <b>KIT-20402046R</b>  | NXH 170 1270 1651 20 SETS |
| <b>KIT-20394998R</b>  | NXH 170 1270 2032 20 SETS |

If you have any questions regarding this communication, please contact your local sales manager or technical application specialist. We are here to help. Thank you for choosing to use KODAK FLEXCEL NX solutions.