

April 3, 2023 Sue Kutay, Global Product Marketing Manager Customers of KODAK FLEXCEL NXH Plates

"

In your upcoming orders, you may notice a slight color shift in your FLEXCEL NXH 1.70 plates. The color shift is cosmetic only and will not impact any performance characteristics of the plate and you should confidently utilize them as normal. We have identified the root cause and taken corrective actions to prevent further instances. Figure 1 illustrates the color shifts that may be observed, you will notice it is most apparent in the raw plate.

Figure 1 Side by side color comparison of the affected product with the reference plate.

Please share this information throughout your operation as appropriate. Continue to use the plates per your normal practice. There is no need to return the plates as the color difference is



Plate and Thickness	Plate Size	Catalog Number	Batch Code
FLEXCEL NX Plate 1.70			31042L12
MM/0.067"	42" x 60"	7873763W	31042L14
	1067 mm x 1524 mm		31042L16
			31042L18
			31042L20
			31042L22
			31052L00
			31052L02
			31052L04
			31052L06
			31052L08

If you have any questions regarding this communication, please contact your local sales manager or technical application specialist.

Thank you once again for both your understanding and your continued business with us.