

## October 1, 2020

From Sue Kutay, Global Product Manager

To: Oustomers and Channel Partners of KODAK FLEXCEL NX Wide System Users

(LAR/USC Region)

Subject: Mbdified packaging for KODAK FLEXCEL NXH Plates in 50' x 80' format


## Tocurvalued customers and channel partners

This notification is for information only. No action is required.

There has been a modification to the standard packaging for the specific batches of KODAK FLEXCEL NXH 1.70mm and 1.14mm plates listed below-this applied to the 5080 size only.

In some boxes foaminserts have been added in the interior of the box to ensure the plate stack is held securely in place. This change is due to a box packaging anomaly where a small gap was observed in the final construction of the box. This modified configuration has been tested and the test confirms that the plates are held securely. Corrective action was taken with the box supplier and future batches will revert to the standard configuration.

The foaminserts are made with polyure thane. Check your local waste management guidelines for disposal.





vww.miradon.com 343 State Street Rochester, NY 14650



What action do I need to take?

